

# INSPECTION REPORT


**End of contract**


## GENERAL INFO

|                               |                                |
|-------------------------------|--------------------------------|
| File                          | 319344                         |
| License plate                 | JJ8180                         |
| Vehicle identification number | ZARPAHBX9M7D06592              |
| Dossier                       | 2020 233 020                   |
| Make                          | Alfa Romeo Stel.2.2MJD 190 Sup |
| Mileage                       | 92240                          |
| First registration            | 04/02/2021                     |
| client availability date      | 03/08/2026                     |
| inspectionDate                | 06/08/2026                     |

## CHECK POINTS

| Description               | Number | Present | Remark |
|---------------------------|--------|---------|--------|
| Original license plate    |        | Y       |        |
| Registration Part 2       |        | N       |        |
| Keys                      | 2      | Y       |        |
| Spare wheel               |        | N       |        |
| Towbar (+keys)            |        | N       |        |
| Certificate of conformity |        | N       |        |
| Registration certificate  |        | N       |        |
| Repair kit                |        | Y       |        |
| RunOnFlat                 |        | N       |        |
| Charging cable            |        | N       |        |
| Charge back wrong tyres   |        | Y       |        |





## DAMAGES

| Damages | Type                                                   | Acceptable |
|---------|--------------------------------------------------------|------------|
| 13      | Bumper Front // Painting                               | N          |
| 234     | Wing Front right // Repair & Painting                  | N          |
| 237     | Wing Front right / Trim / Replace                      | N          |
| 187     | Wing Rear Right / Trim / Replace                       | N          |
| 193     | Door Rear Right // Painting                            | N          |
| 32      | Front Bonnet // Painting                               | Y          |
| 60      | Wing Front Left // Smart Repair Small                  | Y          |
| 80      | Door Front Left // Smart Repair Small                  | Y          |
| 103     | Door Rear Left // Painting                             | Y          |
| 125     | Light / Rear Left On Rear Bonnet / Replace             | Y          |
| 153     | Rear Bonnet // Painting                                | Y          |
| 161     | Roof // Smart Repair Medium                            | Y          |
| 174     | Light / Rear Right / Replace                           | N          |
| 184     | Wing Rear Right // Repair & Painting                   | N          |
| 210     | Door Front Right // Smart Repair Small                 | Y          |
| 228     | Side View Mirror Right / Direction Indicator / Replace | Y          |
| 321     | Wheel Alloy Rear Left // Repair                        | Y          |
| 331     | Wheel Alloy Rear Right // Repair                       | Y          |
| 594     | Trunk Lid Interior Coating / Complete Panel / Replace  | N          |
| 773     | Interior / A Pillar Lower Cover / Replace              | Y          |


## Damage Pictures



Door Front Right // Smart Repair Small-scratch




Side View Mirror Right / Direction Indicator / Replace-scratch



Light / Rear Left On Rear Bonnet / Replace-scratch



Rear Bonnet // Painting-scratch



Light / Rear Right / Replace-scratch



Wheel Alloy Rear Right // Repair-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Interior / A Pillar Lower Cover / Replace-scratch



Roof // Smart Repair Medium-dent



Wing Front Left // Smart Repair Small-dent




Door Front Left // Smart Repair Small-scratch




Door Rear Left // Painting-scratch



Wheel Alloy Rear Left // Repair-scratch



Wing Rear Right // Repair & Painting-scratch + dent




Front Bonnet // Painting-stone chipping



Wing Front right / Trim / Replace-scratch




Bumper Front // Painting-scratch



Wing Front right // Repair & Painting-scratch + dent



Wing Rear Right / Trim / Replace-scratch



Door Rear Right // Painting-scratch