

INSPECTION REPORT


End of contract

GENERAL INFO

File	316954
License plate	2CNW805
Vehicle identification number	YV1XZK7V9P2957687
Dossier	2022019044
Make	Volvo XC40 B3 Core DCT
Mileage	75136
First registration	30/09/2022
client availability date	06/07/2026
inspectionDate	09/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
18	Bumper Front / Spoiler / Replace	N
19	Bumper Front / Lower Cover Not Painted / Replace	N
61	Wing Front Left // Smart Repair Medium	N
67	Wing Front Left / Trim / Replace	N
272	Bumper Front / Trim Right / Replace	N
236	Wing Front right // Polish	Y
237	Wing Front right / Trim / Replace	Y
84	Door Front Left // Repair & Painting	Y
87	Door Front Left / Trim / Replace	Y
91	Rocker Panel Left // Smart Repair Medium	Y
101	Door Rear Left // Smart Repair Medium	N
116	Wing Rear Left // Polish	Y
133	Bumper Rear // Painting	N
138	Bumper Rear / Lower Cover Not Painted / Replace	Y
153	Rear Bonnet // Painting	Y
174	Light / Rear Right / Replace	Y
186	Wing Rear Right // Polish	Y
194	Door Rear Right // Repair & Painting	Y
202	Rocker Panel Right // Painting	Y
213	Door Front Right // Painting	Y
217	Door Front Right / Trim / Replace	Y
222	Side View Mirror Right // Painting	N
311	Wheel Alloy Front Left // Repair	Y
341	Wheel Alloy Front Right // Repair	Y
411	Seat Front Left // Repair	Y
412	Seat Front Left / Bottom Coating / Replace	Y
421	Seat Front Right // Repair	Y
431	Seat Rear Left // Repair	Y
560	Interior / A Pillar Cover / Replace	Y

594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
624	Front Right Door Interior Coating // Replace Completely	Y
644	Rear Right Door Interior Coating // Replace Completely	Y
774	Interior / Side Cover rear Seat / Replace	Y

Damage Pictures



Wheel Alloy Front Right // Repair-scratch



Wheel Alloy Front Left // Repair-scratch



Door Front Right // Painting-scratch



Door Front Right / Trim / Replace-scratch



Side View Mirror Right // Painting-scratch



Door Front Left / Trim / Replace-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Bumper Rear // Painting-scratch



Rear Bonnet // Painting-scratch



Light / Rear Right / Replace-scratch



Wing Rear Right // Polish-scratch



Rocker Panel Right // Painting-scratch



Wing Rear Left // Polish-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Seat Front Right // Repair-scratch



Interior / Side Cover rear Seat / Replace-scratch



Rear Right Door Interior Coating // Replace Completely-scratch



Front Right Door Interior Coating // Replace Completely-scratch



Seat Front Left // Repair-scratch



Seat Rear Left // Repair-scratch




Door Rear Right // Repair & Painting-scratch + dent



Door Front Left // Repair & Painting-scratch + dent



Rocker Panel Left // Smart Repair Medium-scratch + dent



Door Rear Left // Smart Repair Medium-scratch + dent



Seat Front Left / Bottom Coating / Replace-worn



Interior / A Pillar Cover / Replace-hole



Bumper Front / Spoiler / Replace-scratch



Bumper Front / Lower Cover Not Painted / Replace-scratch



Bumper Front / Trim Right / Replace-scratch





Bumper Front // Painting-scratch



Wing Front Left / Trim / Replace-scratch



Wing Front Left // Smart Repair Medium-scratch



Wing Front right / Trim / Replace-scratch



Wing Front right // Polish-scratch