

INSPECTION REPORT



End of contract

GENERAL INFO

File	316302
License plate	2DAU429
Vehicle identification number	TMBER6NW3P3070161
Dossier	2022103086
Make	Skoda Scala 1.0TSI 81kW Clever
Mileage	134679
First registration	18/01/2023
client availability date	01/07/2026
inspectionDate	13/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
891	Lettering Removal 15min	N
12	Bumper Front // Smart Repair Large	N
80	Door Front Left // Smart Repair Small	Y
91	Rocker Panel Left // Smart Repair Medium	Y
100	Door Rear Left // Smart Repair Small	Y
131	Bumper Rear // Smart Repair Medium	Y
190	Door Rear Right // Smart Repair Small	Y
216	Door Front Right // Polish	Y
225	Side View Mirror Right // Polish	Y
236	Wing Front right // Polish	Y
311	Wheel Alloy Front Left // Repair	N
331	Wheel Alloy Rear Right // Repair	N
341	Wheel Alloy Front Right // Repair	N
533	Trunk Compartment / Side Cover Right / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y

Damage Pictures



Wheel Alloy Front Left // Repair-scratch



Door Front Left // Smart Repair Small-scratch



Bumper Rear // Smart Repair Medium-scratch



Wheel Alloy Rear Right // Repair-scratch



Side View Mirror Right // Polish-scratch



Wheel Alloy Front Right // Repair-scratch



Wing Front right // Polish-scratch




Door Front Right // Polish-scratch



Rocker Panel Left // Smart Repair Medium-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Trunk Compartment / Side Cover Right / Replace-scratch



Bumper Front // Smart Repair Large-dent



Door Rear Right // Smart Repair Small-dent



Door Rear Left // Smart Repair Small-dent



Lettering Removal 15min-Remainder stickers