

INSPECTION REPORT

End of contract

GENERAL INFO

File	317636
License plate	2CFT009
Vehicle identification number	VR3F4DGZTNY560112
Dossier	2022053146
Make	Peugeot 508SW 1.6 225 PHEV Act
Mileage	78677
First registration	06/07/2022
client availability date	08/07/2026
inspectionDate	15/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
801	See External Expertise	N
12	Bumper Front // Smart Repair Large	Y
41	Windshield // Replace	Y
66	Wing Front Left // Polish	Y
84	Door Front Left // Repair & Painting	Y
104	Door Rear Left // Repair & Painting	Y
116	Wing Rear Left // Polish	Y
124	Light / Rear left / Replace	Y
125	Light / Rear Left On Rear Bonnet / Replace	Y
136	Bumper Rear // Polish	Y
156	Rear Bonnet // Polish	Y
174	Light / Rear Right / Replace	Y
184	Wing Rear Right // Repair & Painting	Y
196	Door Rear Right // Polish	Y
205	Rocker Panel Right // Polish	Y
214	Door Front Right // Repair & Painting	N
217	Door Front Right / Trim / Replace	Y
236	Wing Front right // Polish	Y
320	Wheel Two Tone Rear Left // Repair	N
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
680	Keys Detachable Towing Hook //	N
860	Interior Cleaning // Small	N

Damage Pictures



Door Rear Left // Repair & Painting-dent



Door Front Left // Repair & Painting-scratch + dent



Door Front Right // Repair & Painting-scratch + dent



Wing Rear Right // Repair & Painting-scratch + dent





Interior Cleaning // Small-stain



Rear Bonnet // Polish-scratch



Bumper Rear // Polish-scratch



Light / Rear Right / Replace-scratch



Light / Rear Left On Rear Bonnet / Replace-scratch



Light / Rear left / Replace-scratch




Wheel Two Tone Rear Right // Repair-scratch



Rocker Panel Right // Polish-scratch




Door Front Right / Trim / Replace-scratch



Door Rear Right // Polish-scratch



Wheel Two Tone Front Right // Repair-scratch



Wing Front right // Polish-scratch



Bumper Front // Smart Repair Large-scratch



Wing Front Left // Polish-scratch



Windshield // Replace-scratch



Wheel Two Tone Rear Left // Repair-scratch






Wing Rear Left // Polish-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch





See External Expertise-dent