

INSPECTION REPORT

End of contract

GENERAL INFO

File	315677
License plate	2CTM530
Vehicle identification number	TMAJE811BNJ120176
Dossier	2022320149
Make	Hyundai Tuc.T-GDi Hyb.169kW Sh
Mileage	188428
First registration	22/11/2022
client availability date	07/07/2026
inspectionDate	15/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
18	Bumper Front / Spoiler / Replace	Y
19	Bumper Front / Lower Cover Not Painted / Replace	Y
135	Bumper Rear // Replace & Painting	N
138	Bumper Rear / Lower Cover Not Painted / Replace	N
139	Bumper Rear / Spoiler / Replace	N
146	Back Side / Reflector L / Replace	N
148	Back Side / Reflector R / Replace	N
154	Rear Bonnet // Repair & Painting	N
157	Rear Bonnet / Trim / Replace	N
159	Rear Bonnet / Rear Window / Replace	N
169	Rear Bonnet / Spoiler / Replace & Painting	N
174	Light / Rear Right / Replace	N
184	Wing Rear Right // Repair & Painting	N
187	Wing Rear Right / Trim / Replace	N
281	Bumper Rear / Trim Left / Replace	N
282	Bumper Rear / Trim Center / Replace	N
283	Bumper Rear / Trim Right / Replace	N
35	Front Bonnet // Polish	Y
40	Windshield // Repair	Y
44	Windshield / Trim / Replace	N
66	Wing Front Left // Polish	Y
84	Door Front Left // Repair & Painting	Y
91	Rocker Panel Left // Smart Repair Medium	Y
104	Door Rear Left // Repair & Painting	Y
116	Wing Rear Left // Polish	Y
161	Roof // Smart Repair Medium	N
162	Roof // Painting	N
194	Door Rear Right // Repair & Painting	N
201	Rocker Panel Right // Smart Repair Medium	N
210	Door Front Right // Smart Repair Small	Y

236	Wing Front right // Polish	Y
310	Wheel Two Tone Front Left // Repair	Y
320	Wheel Two Tone Rear Left // Repair	N
340	Wheel Two Tone Front Right // Repair	Y
411	Seat Front Left // Repair	Y
413	Seat Front Left / Rear Coating / Replace	Y
533	Trunk Compartment / Side Cover Right / Replace	Y
538	Trunk Compartment / Boot Cover / Replace	Y
565	Dashboard / Storage Tray / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
614	Front Left Door Interior Coating // Replace Completely	N
883	Key Price Range 2 //	Y



Damage Pictures





Front Left Door Interior Coating // Replace Completely-hole





Door Rear Right // Repair & Painting-scratch + dent






Rocker Panel Right // Smart Repair Medium-scratch + dent



Door Front Left // Repair & Painting-scratch + dent



Rocker Panel Left // Smart Repair Medium-scratch + dent



Door Rear Left // Repair & Painting-scratch + dent



Windshield // Repair-glass damage



Roof // Painting-Chemical reaction



Seat Front Left / Rear Coating / Replace-worn



Key Price Range 2 //-worn



Windshield / Trim / Replace-bad position



Wing Front right // Polish-scratch



Wheel Two Tone Front Right // Repair-scratch



Front Bonnet // Polish-scratch



Wing Front Left // Polish-scratch



Wheel Two Tone Front Left // Repair-scratch



Wheel Two Tone Rear Left // Repair-scratch




Wing Rear Left // Polish-scratch



Trunk Compartment / Side Cover Right / Replace-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch




Dashboard / Storage Tray / Replace-scratch



Seat Front Left // Repair-scratch



Trunk Compartment / Boot Cover / Replace-dent



Roof // Smart Repair Medium-dent



Door Front Right // Smart Repair Small-dent



Bumper Front / Spoiler / Replace-scratch



Bumper Front / Lower Cover Not Painted / Replace-scratch



Bumper Rear / Trim Left / Replace-scratch



Back Side / Reflector L / Replace-scratch



Bumper Rear / Trim Center / Replace-scratch



Bumper Rear / Trim Right / Replace-scratch



Light / Rear Right / Replace-scratch




Rear Bonnet / Rear Window / Replace-scratch




Bumper Rear // Replace & Painting-cracked



Back Side / Reflector R / Replace-cracked



Bumper Rear / Lower Cover Not Painted / Replace-cracked



Bumper Rear / Spoiler / Replace-cracked




Rear Bonnet / Trim / Replace-cracked





Rear Bonnet / Spoiler / Replace & Painting-scratch + dent



Rear Bonnet // Repair & Painting-scratch + dent



Wing Rear Right // Repair & Painting-scratch + dent



Wing Rear Right / Trim / Replace-bad position