

INSPECTION REPORT



End of contract

GENERAL INFO

File	314886
License plate	2AQV362
Vehicle identification number	W1N2476121W127384
Dossier	2020239100
Make	Mercedes GLB 200d Business Sol
Mileage	168894
First registration	15/06/2021
client availability date	17/06/2026
inspectionDate	07/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	





DAMAGES

Damages	Type	Acceptable
83	Door Front Left // Painting	N
103	Door Rear Left // Painting	N
18	Bumper Front / Spoiler / Replace	N
32	Front Bonnet // Painting	Y
66	Wing Front Left // Polish	Y
91	Rocker Panel Left // Smart Repair Medium	Y
117	Wing Rear Left / Trim / Replace	Y
133	Bumper Rear // Painting	Y
154	Rear Bonnet // Repair & Painting	Y
159	Rear Bonnet / Rear Window / Replace	Y
187	Wing Rear Right / Trim / Replace	Y
201	Rocker Panel Right // Smart Repair Medium	Y
210	Door Front Right // Smart Repair Small	N
569	Dashboard / Steering Wheel / Replace	Y


Damage Pictures



Wing Front Left // Polish-scratch






Door Front Right // Smart Repair Small-dent



Rocker Panel Right // Smart Repair Medium-scratch + dent



Bumper Front / Spoiler / Replace-scratch + dent



Rocker Panel Left // Smart Repair Medium-scratch + dent



Rear Bonnet // Repair & Painting-scratch + dent





Wing Rear Left / Trim / Replace-bad repair



Wing Rear Right / Trim / Replace-bad repair



Front Bonnet // Painting-bad repair



Dashboard / Steering Wheel / Replace-worn



Rear Bonnet / Rear Window / Replace-scratch



Bumper Rear // Painting-scratch



Door Rear Left // Painting-scratch



Door Front Left // Painting-scratch