

INSPECTION REPORT

End of contract

GENERAL INFO

File	315420
License plate	2DVE468
Vehicle identification number	YV1XZBWV5R2224752
Dossier	2022314071
Make	Volvo XC40 T4 PHEV Ult.Dark De
Mileage	163833
First registration	04/07/2023
client availability date	16/06/2026
inspectionDate	10/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
35	Front Bonnet // Polish	Y
40	Windshield // Repair	Y
44	Windshield / Trim / Replace	Y
80	Door Front Left // Smart Repair Small	Y
81	Door Front Left // Smart Repair Medium	Y
133	Bumper Rear // Painting	Y
154	Rear Bonnet // Repair & Painting	N
194	Door Rear Right // Repair & Painting	Y
216	Door Front Right // Polish	Y
236	Wing Front right // Polish	Y
320	Wheel Two Tone Rear Left // Repair	N
340	Wheel Two Tone Front Right // Repair	N
346	Tyre Front Right // Replace	N
538	Trunk Compartment / Boot Cover / Replace	N
638	Rear Left Door Interior Coating / Door Handle / Replace	N
641	Rear Right Door Interior Coating // Repair	N
773	Interior / A Pillar Lower Cover / Replace	Y

Damage Pictures



Bumper Rear // Painting-scratch



Door Front Right // Polish-scratch



Wing Front right // Polish-scratch



Wheel Two Tone Front Right // Repair-scratch




Front Bonnet // Polish-scratch



Windshield / Trim / Replace-scratch



Door Front Left // Smart Repair Medium-scratch



Door Front Left // Smart Repair Small-scratch




Wheel Two Tone Rear Left // Repair-scratch



Rear Right Door Interior Coating // Repair-scratch



Rear Left Door Interior Coating / Door Handle / Replace-scratch




Interior / A Pillar Lower Cover / Replace-scratch




Rear Bonnet // Repair & Painting-scratch + dent



Door Rear Right // Repair & Painting-scratch + dent



Windshield // Repair-glass damage



Trunk Compartment / Boot Cover / Replace-missing



Tyre Front Right // Replace-tear