

INSPECTION REPORT


End of contract

GENERAL INFO

File	319055
License plate	2DEM953
Vehicle identification number	VXKFPHNPLP1008514
Dossier	2022 192 166
Make	Opel Astra 1.2 81kW Edition
Mileage	95637
First registration	22/02/2023
client availability date	30/07/2026
inspectionDate	31/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
18	Bumper Front / Spoiler / Replace	Y
84	Door Front Left // Repair & Painting	Y
92	Rocker Panel Left // Painting	Y
111	Wing Rear Left // Smart Repair Medium	Y
133	Bumper Rear // Painting	Y
150	Rear Bonnet // Smart Repair Small	Y
161	Roof // Smart Repair Medium	Y
163	Roof // Repair & Painting	Y
174	Light / Rear Right / Replace	Y
184	Wing Rear Right // Repair & Painting	Y
210	Door Front Right // Smart Repair Small	Y
219	Door Front Right / Window / Replace	Y
222	Side View Mirror Right // Painting	Y
311	Wheel Alloy Front Left // Repair	Y
321	Wheel Alloy Rear Left // Repair	Y
331	Wheel Alloy Rear Right // Repair	Y
341	Wheel Alloy Front Right // Repair	Y
614	Front Left Door Interior Coating // Replace Completely	Y
860	Interior Cleaning // Small	Y

Damage Pictures



Bumper Rear // Painting-scratch



Side View Mirror Right // Painting-scratch



Wheel Alloy Front Right // Repair-scratch



Bumper Front / Spoiler / Replace-scratch



Wheel Alloy Front Left // Repair-scratch



Rocker Panel Left // Painting-scratch



Wheel Alloy Rear Left // Repair-scratch



Wheel Alloy Rear Right // Repair-scratch



Door Front Right / Window / Replace-scratch



Front Left Door Interior Coating // Replace Completely-scratch



Wing Rear Left // Smart Repair Medium-dent




Roof // Smart Repair Medium-dent




Door Front Left // Repair & Painting-dent








Rear Bonnet // Smart Repair Small-dent



Wing Rear Right // Repair & Painting-scratch + dent



Door Front Right // Smart Repair Small-scratch + dent



Roof // Repair & Painting-bad repair



Light / Rear Right / Replace-cracked



Interior Cleaning // Small-stain