

INSPECTION REPORT






End of contract


GENERAL INFO

File	318739
License plate	2CFT160
Vehicle identification number	TMBJG7NX5NY115846
Dossier	2021 273 141
Make	Skoda Oct.Com.2.0TDI 85kW Clev
Mileage	94054
First registration	06/07/2022
client availability date	24/07/2026
inspectionDate	04/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
801	See External Expertise	N
31	Front Bonnet // Smart Repair Small	Y
41	Windshield // Replace	Y
91	Rocker Panel Left // Smart Repair Medium	Y
106	Door Rear Left // Polish	Y
114	Wing Rear Left // Repair & Painting	N
133	Bumper Rear // Painting	Y
156	Rear Bonnet // Polish	Y
159	Rear Bonnet / Rear Window / Replace	Y
174	Light / Rear Right / Replace	N
180	Wing Rear Right // Smart Repair Small	Y
213	Door Front Right // Painting	Y
236	Wing Front right // Polish	Y
540	Interior // Repair 1	N


Damage Pictures



Front Bonnet // Smart Repair Small-dent



Wing Rear Right // Smart Repair Small-dent




Wing Rear Left // Repair & Painting-scratch + dent





Interior // Repair 1-Incinerated



Light / Rear Right / Replace-scratch



Rear Bonnet / Rear Window / Replace-scratch



Rocker Panel Left // Smart Repair Medium-scratch



Windshield // Replace-scratch



Wing Front right // Polish-scratch



Door Rear Left // Polish-scratch






Rear Bonnet // Polish-scratch



Bumper Rear // Painting-scratch



Door Front Right // Painting-scratch



See External Expertise-dent