

INSPECTION REPORT

End of contract

GENERAL INFO

File	317074
License plate	2BUS991
Vehicle identification number	TMBJN7NP6N7037461
Dossier	2021273163
Make	Skoda Sup.Comb.TSI 150 Clever
Mileage	58626
First registration	30/03/2022
client availability date	02/07/2026
inspectionDate	08/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
12	Bumper Front // Smart Repair Large	N
31	Front Bonnet // Smart Repair Small	Y
103	Door Rear Left // Painting	Y
110	Wing Rear Left // Smart Repair Small	N
135	Bumper Rear // Replace & Painting	N
201	Rocker Panel Right // Smart Repair Medium	Y
346	Tyre Front Right // Replace	N
860	Interior Cleaning // Small	N

Damage Pictures



Door Rear Left // Painting-scratch




Bumper Front // Smart Repair Large-scratch



Rocker Panel Right // Smart Repair Medium-scratch



Wing Rear Left // Smart Repair Small-dent



Front Bonnet // Smart Repair Small-dent



Bumper Rear // Replace & Painting-cracked



Tyre Front Right // Replace-tear



Interior Cleaning // Small-stain