

INSPECTION REPORT



End of contract

GENERAL INFO

File	316924
License plate	2FPB147
Vehicle identification number	TMAJB812DPJ263600
Dossier	2024147002
Make	Hyundai Tuc.TGDï PHEV 195kW 4x
Mileage	41949
First registration	28/06/2024
client availability date	01/07/2026
inspectionDate	09/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
18	Bumper Front / Spoiler / Replace	Y
35	Front Bonnet // Polish	Y
72	Side View Mirror Left // Painting	Y
78	Side View Mirror Left / Direction Indicator / Replace	Y
91	Rocker Panel Left // Smart Repair Medium	N
103	Door Rear Left // Painting	Y
107	Door Rear Left / Trim / Replace	N
116	Wing Rear Left // Polish	Y
117	Wing Rear Left / Trim / Replace	Y
133	Bumper Rear // Painting	Y
138	Bumper Rear / Lower Cover Not Painted / Replace	Y
139	Bumper Rear / Spoiler / Replace	Y
183	Wing Rear Right // Painting	N
196	Door Rear Right // Polish	Y
201	Rocker Panel Right // Smart Repair Medium	N
213	Door Front Right // Painting	Y
222	Side View Mirror Right // Painting	N
271	Bumper Front / Trim Left / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y

Damage Pictures




Door Rear Left // Painting-scratch



Side View Mirror Left / Direction Indicator / Replace-scratch



Side View Mirror Left // Painting-scratch



Front Bonnet // Polish-scratch



Bumper Front / Trim Left / Replace-scratch



Bumper Front // Painting-scratch



Bumper Front / Spoiler / Replace-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch





Bumper Rear / Lower Cover Not Painted / Replace-scratch




Bumper Rear / Spoiler / Replace-scratch




Bumper Rear // Painting-scratch



Side View Mirror Right // Painting-scratch



Door Front Right // Painting-scratch



Door Rear Right // Polish-scratch




Wing Rear Right // Painting-scratch



Wing Rear Left // Polish-scratch



Wing Rear Left / Trim / Replace-scratch



Rocker Panel Left // Smart Repair Medium-scratch + dent



Rocker Panel Right // Smart Repair Medium-scratch + dent



Door Rear Left / Trim / Replace-bad repair