

INSPECTION REPORT


End of contract

GENERAL INFO

File	318065
License plate	2CHM223
Vehicle identification number	W1K1186861N323044
Dossier	2021237011
Make	Mercedes CLA SB 250 e Bus.Solu
Mileage	127969
First registration	29/07/2022
client availability date	14/07/2026
inspectionDate	28/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		Y	






DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	Y
54	Headlight / Front left / Replace	N
81	Door Front Left // Smart Repair Medium	N
91	Rocker Panel Left // Smart Repair Medium	N
103	Door Rear Left // Painting	N
161	Roof // Smart Repair Medium	Y
184	Wing Rear Right // Repair & Painting	Y
201	Rocker Panel Right // Smart Repair Medium	N
217	Door Front Right / Trim / Replace	N
233	Wing Front right // Painting	Y
310	Wheel Two Tone Front Left // Repair	Y
320	Wheel Two Tone Rear Left // Repair	N
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	Y
411	Seat Front Left // Repair	N
538	Trunk Compartment / Boot Cover / Replace	N
540	Interior // Repair 1	N
569	Dashboard / Steering Wheel / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
614	Front Left Door Interior Coating // Replace Completely	Y
850	Certificate of Conformity //	N
860	Interior Cleaning // Small	N

Damage Pictures



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Wheel Two Tone Rear Left // Repair-scratch



Seat Front Left // Repair-scratch



Front Left Door Interior Coating // Replace Completely-scratch



Wheel Two Tone Front Left // Repair-scratch



Headlight / Front left / Replace-scratch



Bumper Front // Painting-scratch



Wing Front right // Painting-scratch



Wheel Two Tone Rear Right // Repair-scratch




Roof // Smart Repair Medium-dent



Wing Rear Right // Repair & Painting-dent



Rocker Panel Right // Smart Repair Medium-scratch + dent




Rocker Panel Left // Smart Repair Medium-scratch + dent



Door Front Left // Smart Repair Medium-scratch + dent



Door Front Right / Trim / Replace-scratch + dent



Door Rear Left // Painting-bad repair



Trunk Compartment / Boot Cover / Replace-missing



Wheel Two Tone Front Right // Repair-Chemical reaction



Interior Cleaning // Small-stain



Dashboard / Steering Wheel / Replace-worn



Interior // Repair 1-bad position