

INSPECTION REPORT







End of contract

GENERAL INFO

File	316617
License plate	2APB177
Vehicle identification number	TMBJF7NU1M5052351
Dossier	2021029119
Make	Skoda Karoq 2.0TDi 85kW Clever
Mileage	123843
First registration	31/05/2021
client availability date	01/07/2026
inspectionDate	03/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
64	Wing Front Left // Repair & Painting	Y
72	Side View Mirror Left // Painting	N
84	Door Front Left // Repair & Painting	Y
138	Bumper Rear / Lower Cover Not Painted / Replace	Y
186	Wing Rear Right // Polish	Y
194	Door Rear Right // Repair & Painting	N
214	Door Front Right // Repair & Painting	Y
222	Side View Mirror Right // Painting	Y
540	Interior // Repair 1	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
631	Rear Left Door Interior Coating // Repair	N

Damage Pictures



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Side View Mirror Left // Painting-scratch



Side View Mirror Right // Painting-scratch



Wing Rear Right // Polish-scratch




Door Front Left // Repair & Painting-scratch + dent



Door Front Right // Repair & Painting-scratch + dent



Door Rear Right // Repair & Painting-scratch + dent



Wing Front Left // Repair & Painting-scratch + dent



Bumper Rear / Lower Cover Not Painted / Replace-scratch + dent



Rear Left Door Interior Coating // Repair-cracked



Interior // Repair 1-Incinerated