

INSPECTION REPORT


End of contract

GENERAL INFO

File	316578
License plate	2CEA259
Vehicle identification number	VF3MCYHZUNS099359
Dossier	2021 333 131
Make	Peugeot 5008 1.5BHdi 96kW Allu
Mileage	127789
First registration	20/06/2022
client availability date	07/07/2026
inspectionDate	16/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
12	Bumper Front // Smart Repair Large	Y
80	Door Front Left // Smart Repair Small	Y
91	Rocker Panel Left // Smart Repair Medium	Y
116	Wing Rear Left // Polish	Y
138	Bumper Rear / Lower Cover Not Painted / Replace	Y
153	Rear Bonnet // Painting	Y
225	Side View Mirror Right // Polish	Y
320	Wheel Two Tone Rear Left // Repair	Y
413	Seat Front Left / Rear Coating / Replace	Y
569	Dashboard / Steering Wheel / Replace	Y
680	Keys Detachable Towing Hook //	Y

Damage Pictures



Wing Rear Left // Polish-scratch



Bumper Front // Smart Repair Large-scratch



Wheel Two Tone Rear Left // Repair-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Rear Bonnet // Painting-scratch



Side View Mirror Right // Polish-scratch



Door Front Left // Smart Repair Small-dent



Rocker Panel Left // Smart Repair Medium-dent



Seat Front Left / Rear Coating / Replace-worn



Dashboard / Steering Wheel / Replace-worn