

INSPECTION REPORT

End of contract

GENERAL INFO

File	318896
License plate	JV5906
Vehicle identification number	VR3USHN5SNJ662361
Dossier	2021342100
Make	Peugeot 2008 1.2 PT 130 Allure
Mileage	55517
First registration	28/07/2022
client availability date	28/07/2026
inspectionDate	04/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
891	Lettering Removal 15min	N
84	Door Front Left // Repair & Painting	Y
91	Rocker Panel Left // Smart Repair Medium	Y
124	Light / Rear left / Replace	Y
125	Light / Rear Left On Rear Bonnet / Replace	Y
136	Bumper Rear // Polish	Y
156	Rear Bonnet // Polish	Y
159	Rear Bonnet / Rear Window / Replace	Y
161	Roof // Smart Repair Medium	N
193	Door Rear Right // Painting	N
210	Door Front Right // Smart Repair Small	Y
222	Side View Mirror Right // Painting	Y
860	Interior Cleaning // Small	N


Damage Pictures



Side View Mirror Right // Painting-scratch




Rear Bonnet // Polish-scratch





Bumper Rear // Polish-scratch



Light / Rear Left On Rear Bonnet / Replace-scratch



Light / Rear left / Replace-scratch



Rear Bonnet / Rear Window / Replace-scratch




Door Front Right // Smart Repair Small-scratch




Rocker Panel Left // Smart Repair Medium-dent



Door Front Left // Repair & Painting-scratch + dent



Roof // Smart Repair Medium-scratch + dent



Door Rear Right // Painting-bad repair



Interior Cleaning // Small-stain



Lettering Removal 15min-