

INSPECTION REPORT

End of contract


GENERAL INFO

File	318048
License plate	HK5228
Vehicle identification number	VR3UBYHTKP5065604
Dossier	2022329008
Make	Peugeot 208 1.5BHD102 Allure
Mileage	43595
First registration	05/07/2023
client availability date	14/07/2026
inspectionDate	18/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	






DAMAGES

Damages	Type	Acceptable
801	See External Expertise	N
41	Windshield // Replace	Y
80	Door Front Left // Smart Repair Small	Y
103	Door Rear Left // Painting	Y
159	Rear Bonnet / Rear Window / Replace	Y
191	Door Rear Right // Smart Repair Medium	N
213	Door Front Right // Painting	N
310	Wheel Two Tone Front Left // Repair	Y
340	Wheel Two Tone Front Right // Repair	N
540	Interior // Repair 1	N
560	Interior / A Pillar Cover / Replace	N
860	Interior Cleaning // Small	N

Damage Pictures



See External Expertise-



Interior / A Pillar Cover / Replace-scratch



Rear Bonnet / Rear Window / Replace-scratch




Door Rear Left // Painting-scratch



Door Front Left // Smart Repair Small-scratch




Wheel Two Tone Front Right // Repair-scratch






Door Rear Right // Smart Repair Medium-dent



Door Front Right // Painting-scratch + dent




Windshield // Replace-cracked



Interior // Repair 1-missing



Wheel Two Tone Front Left // Repair-Chemical reaction



Interior Cleaning // Small-stain