

INSPECTION REPORT



End of contract

GENERAL INFO

File	316055
License plate	2BDK981
Vehicle identification number	W1N1671171A561758
Dossier	2021 151 195
Make	Mercedes GLE 350 de 4M Bus.Sol
Mileage	215125
First registration	12/10/2021
client availability date	10/07/2026
inspectionDate	17/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
40	Windshield // Repair	Y
80	Door Front Left // Smart Repair Small	Y
91	Rocker Panel Left // Smart Repair Medium	Y
103	Door Rear Left // Painting	Y
110	Wing Rear Left // Smart Repair Small	Y
117	Wing Rear Left / Trim / Replace	Y
186	Wing Rear Right // Polish	Y
210	Door Front Right // Smart Repair Small	Y
320	Wheel Two Tone Rear Left // Repair	Y
561	Dashboard // Repair	Y
631	Rear Left Door Interior Coating // Repair	N

Damage Pictures



Wheel Two Tone Rear Left // Repair-scratch



Wing Rear Left / Trim / Replace-scratch





Door Rear Left // Painting-scratch



Dashboard // Repair-scratch



Wing Rear Right // Polish-scratch



Door Front Right // Smart Repair Small-scratch



Door Front Left // Smart Repair Small-dent



Wing Rear Left // Smart Repair Small-dent



Rocker Panel Left // Smart Repair Medium-scratch + dent



Windshield // Repair-cracked



Rear Left Door Interior Coating // Repair-tear