

INSPECTION REPORT




End of contract

GENERAL INFO

File	316491
License plate	2CAV231
Vehicle identification number	W1N2436081N010923
Dossier	2022 046 106
Make	Mercedes EQB 300 4M Luxury Lin
Mileage	80384
First registration	13/05/2022
client availability date	10/07/2026
inspectionDate	17/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
191	Door Rear Right // Smart Repair Medium	N
213	Door Front Right // Painting	N
233	Wing Front right // Painting	N
237	Wing Front right / Trim / Replace	N
133	Bumper Rear // Painting	N
138	Bumper Rear / Lower Cover Not Painted / Replace	N
159	Rear Bonnet / Rear Window / Replace	Y
174	Light / Rear Right / Replace	Y
186	Wing Rear Right // Polish	Y
320	Wheel Two Tone Rear Left // Repair	Y
340	Wheel Two Tone Front Right // Repair	Y
532	Trunk Compartment / Side Cover Left / Replace	Y
543	Interior // Ionization Odor	Y


Damage Pictures



Wheel Two Tone Rear Left // Repair-scratch



Wheel Two Tone Front Right // Repair-scratch



Wing Rear Right // Polish-scratch



Trunk Compartment / Side Cover Left / Replace-scratch




Light / Rear Right / Replace-scratch



Rear Bonnet / Rear Window / Replace-scratch



Door Rear Right // Smart Repair Medium-scratch



Door Front Right // Painting-scratch



Wing Front right / Trim / Replace-scratch



Wing Front right // Painting-scratch



Bumper Rear // Painting-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch