

INSPECTION REPORT


End of contract

GENERAL INFO

File	316873
License plate	1YDH144
Vehicle identification number	YV1XZL4V1M2415383
Dossier	2020149095
Make	Volvo XC40 T2 Momentum Pro
Mileage	122738
First registration	27/07/2020
client availability date	07/07/2026
inspectionDate	17/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	







DAMAGES

Damages	Type	Acceptable
801	See External Expertise	N
63	Wing Front Left // Painting	Y
67	Wing Front Left / Trim / Replace	N
80	Door Front Left // Smart Repair Small	Y
91	Rocker Panel Left // Smart Repair Medium	Y
133	Bumper Rear // Painting	Y
138	Bumper Rear / Lower Cover Not Painted / Replace	N
156	Rear Bonnet // Polish	Y
201	Rocker Panel Right // Smart Repair Medium	N
311	Wheel Alloy Front Left // Repair	N
321	Wheel Alloy Rear Left // Repair	N
331	Wheel Alloy Rear Right // Repair	N
341	Wheel Alloy Front Right // Repair	Y
413	Seat Front Left / Rear Coating / Replace	Y
423	Seat Front Right / Rear Coating / Replace	Y
540	Interior // Repair 1	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
634	Rear Left Door Interior Coating // Replace Completely	Y
860	Interior Cleaning // Small	N

Damage Pictures





Rocker Panel Right // Smart Repair Medium-scratch + dent



Interior // Repair 1-cracked



Bumper Rear / Lower Cover Not Painted / Replace-cracked




Interior Cleaning // Small-dirty



Seat Front Right / Rear Coating / Replace-scratch




Seat Front Left / Rear Coating / Replace-scratch



Rocker Panel Left // Smart Repair Medium-scratch



Wheel Alloy Front Left // Repair-scratch



Wheel Alloy Rear Left // Repair-scratch



Door Front Left // Smart Repair Small-scratch



Wing Front Left // Painting-scratch



Wing Front Left / Trim / Replace-scratch



Bumper Rear // Painting-scratch



Rear Left Door Interior Coating // Replace Completely-scratch




Rear Bonnet // Polish-scratch




Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Wheel Alloy Rear Right // Repair-scratch



Wheel Alloy Front Right // Repair-scratch



See External Expertise-dent