

INSPECTION REPORT




End of contract

GENERAL INFO

File	314789
License plate	1XGU702
Vehicle identification number	VR3ECYHZJKJ891444
Dossier	2019 204 167
Make	Peugeot Rifter 1.5BHDi 130 All
Mileage	182149
First registration	02/01/2020
client availability date	12/06/2026
inspectionDate	13/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
271	Bumper Front / Trim Left / Replace	N
18	Bumper Front / Spoiler / Replace	Y
40	Windshield // Repair	Y
80	Door Front Left // Smart Repair Small	Y
91	Rocker Panel Left // Smart Repair Medium	N
103	Door Rear Left // Painting	N
137	Bumper Rear // Replace without painting	Y
159	Rear Bonnet / Rear Window / Replace	Y
184	Wing Rear Right // Repair & Painting	Y
187	Wing Rear Right / Trim / Replace	Y
196	Door Rear Right // Polish	Y
197	Door Rear Right / Trim / Replace	Y
201	Rocker Panel Right // Smart Repair Medium	Y
208	Rocker Panel Right / Cover Not Painted / Replace	Y
216	Door Front Right // Polish	Y
222	Side View Mirror Right // Painting	N
272	Bumper Front / Trim Right / Replace	Y
314	Wheel Front Left / Wheel Cover / Replace	N
324	Wheel Rear Left / Wheel Cover / Replace	N
334	Wheel Rear Right / Wheel Cover / Replace	N
441	Seat Rear Central // Repair	N
532	Trunk Compartment / Side Cover Left / Replace	Y
533	Trunk Compartment / Side Cover Right / Replace	Y
860	Interior Cleaning // Small	N


Damage Pictures



Wheel Front Left / Wheel Cover / Replace-scratch



Door Front Left // Smart Repair Small-scratch




Door Rear Left // Painting-scratch



Wheel Rear Left / Wheel Cover / Replace-scratch



Bumper Rear // Replace without painting-scratch



Rocker Panel Right // Smart Repair Medium-dent



Rocker Panel Left // Smart Repair Medium-scratch + dent



Wing Rear Right // Repair & Painting-scratch + dent



Windshield // Repair-cracked



Seat Rear Central // Repair-tear



Interior Cleaning // Small-stain



Rear Bonnet / Rear Window / Replace-scratch



Rocker Panel Right / Cover Not Painted / Replace-scratch



Bumper Front / Spoiler / Replace-scratch



Trunk Compartment / Side Cover Right / Replace-scratch




Trunk Compartment / Side Cover Left / Replace-scratch



Wing Rear Right / Trim / Replace-scratch



Door Rear Right / Trim / Replace-scratch



Door Rear Right // Polish-scratch



Wheel Rear Right / Wheel Cover / Replace-scratch



Door Front Right // Polish-scratch



Side View Mirror Right // Painting-scratch



Bumper Front / Trim Right / Replace-scratch



Bumper Front // Painting-scratch



Bumper Front / Trim Left / Replace-scratch