

INSPECTION REPORT


End of contract


GENERAL INFO

File	315911
License plate	2DBS236
Vehicle identification number	ZACPJFCWXNPS26687
Dossier	2022166016
Make	Jeep Com.1.3PHEV 190 4xe Limit
Mileage	110599
First registration	27/01/2023
client availability date	02/07/2026
inspectionDate	09/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
561	Dashboard // Repair	Y
565	Dashboard / Storage Tray / Replace	Y
197	Door Rear Right / Trim / Replace	Y
210	Door Front Right // Smart Repair Small	Y
217	Door Front Right / Trim / Replace	Y
165	Roof // Polish	Y
169	Rear Bonnet / Spoiler / Replace & Painting	Y
35	Front Bonnet // Polish	Y
43	Windshield / Whiper Arm / Replace	N
64	Wing Front Left // Repair & Painting	Y
72	Side View Mirror Left // Painting	N
80	Door Front Left // Smart Repair Small	Y
91	Rocker Panel Left // Smart Repair Medium	Y
104	Door Rear Left // Repair & Painting	N
110	Wing Rear Left // Smart Repair Small	N
134	Bumper Rear // Repair & Painting	Y
138	Bumper Rear / Lower Cover Not Painted / Replace	Y
159	Rear Bonnet / Rear Window / Replace	Y
161	Roof // Smart Repair Medium	Y
180	Wing Rear Right // Smart Repair Small	Y
194	Door Rear Right // Repair & Painting	Y
201	Rocker Panel Right // Smart Repair Medium	Y
310	Wheel Two Tone Front Left // Repair	N
320	Wheel Two Tone Rear Left // Repair	N
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	N
554	Central Console // Replace Completely	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
638	Rear Left Door Interior Coating / Door Handle / Replace	Y


Damage Pictures




Bumper Rear / Lower Cover Not Painted / Replace-scratch



Rear Bonnet / Rear Window / Replace-scratch



Central Console // Replace Completely-scratch



Wing Rear Left // Smart Repair Small-dent




Rocker Panel Left // Smart Repair Medium-dent



Roof // Smart Repair Medium-dent



Wing Rear Right // Smart Repair Small-dent





Rocker Panel Right // Smart Repair Medium-scratch + dent




Bumper Rear // Repair & Painting-scratch + dent



Wing Front Left // Repair & Painting-scratch + dent





Door Rear Right // Repair & Painting-scratch + dent



Door Rear Left // Repair & Painting-scratch + dent




Windshield / Whiper Arm / Replace-Chipped paint




Wheel Two Tone Rear Right // Repair-scratch




Wheel Two Tone Front Right // Repair-scratch



Front Bonnet // Polish-scratch



Wheel Two Tone Front Left // Repair-scratch



Side View Mirror Left // Painting-scratch



Door Front Left // Smart Repair Small-scratch



Rear Left Door Interior Coating / Door Handle / Replace-scratch



Wheel Two Tone Rear Left // Repair-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Dashboard // Repair-scratch



Dashboard / Storage Tray / Replace-scratch




Door Front Right / Trim / Replace-scratch




Door Rear Right / Trim / Replace-scratch



Door Front Right // Smart Repair Small-dent



Roof // Polish-scratch



Rear Bonnet / Spoiler / Replace & Painting-scratch