

INSPECTION REPORT

End of contract

GENERAL INFO

File	316980
License plate	2CER446
Vehicle identification number	VF3M45GBUNS070300
Dossier	2021 313 011
Make	Peugeot 3008 PHEV 220kW GT Aut
Mileage	129803
First registration	27/06/2022
client availability date	06/07/2026
inspectionDate	11/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	1	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
12	Bumper Front // Smart Repair Large	N
13	Bumper Front // Painting	N
22	Front / Daytime Running Lights Right / Replace	N
272	Bumper Front / Trim Right / Replace	N
44	Windshield / Trim / Replace	Y
165	Roof // Polish	Y
27	Front / Logo / Replace	N
32	Front Bonnet // Painting	Y
75	Side View Mirror Left // Polish	Y
84	Door Front Left // Repair & Painting	N
100	Door Rear Left // Smart Repair Small	Y
159	Rear Bonnet / Rear Window / Replace	N
161	Roof // Smart Repair Medium	Y
201	Rocker Panel Right // Smart Repair Medium	N
310	Wheel Two Tone Front Left // Repair	N
320	Wheel Two Tone Rear Left // Repair	N
330	Wheel Two Tone Rear Right // Repair	Y
340	Wheel Two Tone Front Right // Repair	N
540	Interior // Repair 1	Y
860	Interior Cleaning // Small	N
883	Key Price Range 2 //	N


Damage Pictures



Door Rear Left // Smart Repair Small-dent



Door Front Left // Repair & Painting-dent




Roof // Smart Repair Medium-dent



Rocker Panel Right // Smart Repair Medium-scratch + dent



Front / Logo / Replace-cracked



Interior Cleaning // Small-stain



Front Bonnet // Painting-Chipped paint




Wheel Two Tone Front Left // Repair-scratch



Wheel Two Tone Rear Left // Repair-scratch



Wheel Two Tone Rear Right // Repair-scratch



Rear Bonnet / Rear Window / Replace-scratch



Side View Mirror Left // Polish-scratch



Interior // Repair 1-



Wheel Two Tone Front Right // Repair-scratch



Bumper Front // Painting-scratch



Bumper Front / Trim Right / Replace-scratch



Front / Daytime Running Lights Right / Replace-scratch



Bumper Front // Smart Repair Large-scratch + dent



Roof // Polish-scratch



Windshield / Trim / Replace-scratch