

INSPECTION REPORT


End of contract

GENERAL INFO

File	316622
License plate	2CEN006
Vehicle identification number	W0VEFYHZ2NJ618029
Dossier	2021 148 185
Make	Opel Comb.1.5D 96kW 2.3T L2H1
Mileage	71179
First registration	24/06/2022
client availability date	01/07/2026
inspectionDate	14/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	Y
41	Windshield // Replace	Y
54	Headlight / Front left / Replace	N
63	Wing Front Left // Painting	Y
77	Side View Mirror Left / Shell / Replace Not Painted	Y
114	Wing Rear Left // Repair & Painting	N
138	Bumper Rear / Lower Cover Not Painted / Replace	Y
183	Wing Rear Right // Painting	N
214	Door Front Right // Repair & Painting	N
227	Side View Mirror Right / Shell / Replace Not Painted	Y
294	Rear Loading Door Left // Repair & Painting	N
304	Rear Loading Door Right // Repair & Painting	N
619	Front Left Door Interior Coating / Control Module / Replace	N
860	Interior Cleaning // Small	N


Damage Pictures



Windshield // Replace-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Side View Mirror Left / Shell / Replace Not Painted-scratch




Wing Front Left // Painting-scratch




Headlight / Front left / Replace-scratch



Bumper Front // Painting-scratch



Side View Mirror Right / Shell / Replace Not Painted-scratch




Wing Rear Right // Painting-scratch



Door Front Right // Repair & Painting-scratch + dent



Wing Rear Left // Repair & Painting-scratch + dent



Rear Loading Door Right // Repair & Painting-scratch + dent



Rear Loading Door Left // Repair & Painting-scratch + dent



Front Left Door Interior Coating / Control Module / Replace-bad repair



Interior Cleaning // Small-stain