

INSPECTION REPORT




End of contract

GENERAL INFO

File	317857
License plate	2DHQ498
Vehicle identification number	VF3MRHNSUPS037723
Dossier	2022 285 092
Make	Peugeot 5008 1.2PTech 96kW Act
Mileage	219774
First registration	22/03/2023
client availability date	16/07/2026
inspectionDate	24/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
12	Bumper Front // Smart Repair Large	N
19	Bumper Front / Lower Cover Not Painted / Replace	N
237	Wing Front right / Trim / Replace	N
154	Rear Bonnet // Repair & Painting	N
157	Rear Bonnet / Trim / Replace	N
187	Wing Rear Right / Trim / Replace	N
194	Door Rear Right // Repair & Painting	N
138	Bumper Rear / Lower Cover Not Painted / Replace	N
258	Towing Cover Rear // Replace	N
18	Bumper Front / Spoiler / Replace	Y
67	Wing Front Left / Trim / Replace	Y
81	Door Front Left // Smart Repair Medium	N
91	Rocker Panel Left // Smart Repair Medium	Y
101	Door Rear Left // Smart Repair Medium	Y
116	Wing Rear Left // Polish	Y
159	Rear Bonnet / Rear Window / Replace	Y
184	Wing Rear Right // Repair & Painting	N
201	Rocker Panel Right // Smart Repair Medium	N
214	Door Front Right // Repair & Painting	Y
217	Door Front Right / Trim / Replace	N
311	Wheel Alloy Front Left // Repair	N
321	Wheel Alloy Rear Left // Repair	Y
331	Wheel Alloy Rear Right // Repair	N
341	Wheel Alloy Front Right // Repair	N
774	Interior / Side Cover rear Seat / Replace	N

Damage Pictures



Rocker Panel Right // Smart Repair Medium-scratch + dent



Rocker Panel Left // Smart Repair Medium-scratch



Wheel Alloy Front Right // Repair-scratch



Door Front Right / Trim / Replace-scratch



Wheel Alloy Rear Right // Repair-scratch



Wing Rear Right // Repair & Painting-scratch



Door Rear Left // Smart Repair Medium-dent



Door Front Right // Repair & Painting-scratch + dent



Interior / Side Cover rear Seat / Replace-scratch



Rear Bonnet / Rear Window / Replace-scratch



Wheel Alloy Rear Left // Repair-scratch



Wing Rear Left // Polish-scratch



Door Front Left // Smart Repair Medium-scratch



Wing Front Left / Trim / Replace-scratch



Wheel Alloy Front Left // Repair-scratch



Bumper Front / Spoiler / Replace-scratch



Bumper Front / Lower Cover Not Painted / Replace-scratch



Bumper Front // Smart Repair Large-scratch




Wing Front right / Trim / Replace-scratch




Towing Cover Rear // Replace-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch + dent





Rear Bonnet / Trim / Replace-scratch



Rear Bonnet // Repair & Painting-scratch + dent



Wing Rear Right / Trim / Replace-scratch



Door Rear Right // Repair & Painting-scratch