

INSPECTION REPORT

End of contract

GENERAL INFO

File	316377
License plate	2EUD616
Vehicle identification number	TMBJP8NX6RY118380
Dossier	2023100006
Make	Skoda Oct.Com.1.0 eTec 81kW Cl
Mileage	28071
First registration	30/01/2024
client availability date	26/06/2026
inspectionDate	14/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	3	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	





DAMAGES

Damages	Type	Acceptable
14	Bumper Front // Repair & Painting	N
133	Bumper Rear // Painting	N
340	Wheel Two Tone Front Right // Repair	N

Damage Pictures



Bumper Rear // Painting-scratch



Wheel Two Tone Front Right // Repair-scratch



Bumper Front // Repair & Painting-scratch + dent