

INSPECTION REPORT



End of contract

GENERAL INFO

File	313035
License plate	2CBL699
Vehicle identification number	TMAJD81AANJ185774
Dossier	2022 136 086
Make	Hyundai Tuc.CRD 48V 100kW Fee
Mileage	148528
First registration	20/05/2022
client availability date	26/05/2026
inspectionDate	14/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
29	Front / Park Assist Sensor / Replace	Y
33	Front Bonnet // Repair & Painting	Y
95	Rocker Panel Left // Polish	Y
116	Wing Rear Left // Polish	Y
136	Bumper Rear // Polish	Y
139	Bumper Rear / Spoiler / Replace	Y
152	Rear Bonnet // Smart Repair Large	N
161	Roof // Smart Repair Medium	Y
183	Wing Rear Right // Painting	Y
196	Door Rear Right // Polish	Y
205	Rocker Panel Right // Polish	Y
216	Door Front Right // Polish	Y
236	Wing Front right // Polish	Y
330	Wheel Two Tone Rear Right // Repair	Y

Damage Pictures



Wing Front right // Polish-scratch



Door Front Right // Polish-scratch



Rocker Panel Left // Polish-scratch



Bumper Rear / Spoiler / Replace-scratch



Wing Rear Left // Polish-scratch



Door Rear Right // Polish-scratch



Rocker Panel Right // Polish-scratch




Bumper Rear // Polish-scratch



Wheel Two Tone Rear Right // Repair-scratch



Wing Rear Right // Painting-scratch



Roof // Smart Repair Medium-dent



Bumper Front // Painting-bad repair



Rear Bonnet // Smart Repair Large-bad repair



Front Bonnet // Repair & Painting-rust



Front / Park Assist Sensor / Replace-Chipped paint