

INSPECTION REPORT


End of contract

GENERAL INFO

File	319338
License plate	PH9519
Vehicle identification number	VR3ECYHZRLJ838572
Dossier	2020 176 018
Make	Peugeot Rifter MWD HDi130 L AI
Mileage	10871
First registration	07/06/2021
client availability date	03/08/2026
inspectionDate	10/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	






DAMAGES

Damages	Type	Acceptable
93	Rocker Panel Left // Repair & Painting	N
98	Rocker Panel Left / Cover Not Painted / Replace	N
35	Front Bonnet // Polish	Y
63	Wing Front Left // Painting	Y
80	Door Front Left // Smart Repair Small	Y
103	Door Rear Left // Painting	Y
113	Wing Rear Left // Painting	Y
154	Rear Bonnet // Repair & Painting	Y
165	Roof // Polish	Y
183	Wing Rear Right // Painting	Y
187	Wing Rear Right / Trim / Replace	N
193	Door Rear Right // Painting	Y
568	Dashboard / Ventilation Outlet / Replace	N

Damage Pictures



Dashboard / Ventilation Outlet / Replace-missing



Roof // Polish-scratch



Door Rear Right // Painting-scratch



Wing Rear Right // Painting-scratch



Wing Rear Right / Trim / Replace-scratch



Door Front Left // Smart Repair Small-scratch



Wing Rear Left // Painting-scratch



Door Rear Left // Painting-scratch



Wing Front Left // Painting-scratch



Front Bonnet // Polish-scratch



Rear Bonnet // Repair & Painting-scratch + dent



Rocker Panel Left // Repair & Painting-scratch + dent



Rocker Panel Left / Cover Not Painted / Replace-missing