

INSPECTION REPORT


End of contract

GENERAL INFO

File	316041
License plate	2AWN907
Vehicle identification number	TMBER6NW3N3011821
Dossier	2021092070
Make	Skoda Scala 1.0TSI 81kW Clever
Mileage	152876
First registration	17/08/2021
client availability date	01/07/2026
inspectionDate	13/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
73	Side View Mirror Left // Replace Not Painted	N
76	Side View Mirror Left / Shell / Replace Painted	N
78	Side View Mirror Left / Direction Indicator / Replace	N
186	Wing Rear Right // Polish	Y
196	Door Rear Right // Polish	Y
654	Lettering Removal 15min	N
13	Bumper Front // Painting	N
35	Front Bonnet // Polish	Y
66	Wing Front Left // Polish	N
80	Door Front Left // Smart Repair Small	Y
106	Door Rear Left // Polish	Y
113	Wing Rear Left // Painting	Y
133	Bumper Rear // Painting	N
159	Rear Bonnet / Rear Window / Replace	N
161	Roof // Smart Repair Medium	N
202	Rocker Panel Right // Painting	Y
211	Door Front Right // Smart Repair Medium	N
223	Side View Mirror Right // Replace Not Painted	N
225	Side View Mirror Right // Polish	N
236	Wing Front right // Polish	N
273	Bumper Front / Grid Left / Replace	N
275	Bumper Front / Grid Right / Replace	N
321	Wheel Alloy Rear Left // Repair	N
331	Wheel Alloy Rear Right // Repair	N
341	Wheel Alloy Front Right // Repair	N
554	Central Console // Replace Completely	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
624	Front Right Door Interior Coating // Replace Completely	N


Damage Pictures



Front Bonnet // Polish-Chemical reaction



Side View Mirror Right // Replace Not Painted-cracked



Bumper Front / Grid Left / Replace-cracked



Wheel Alloy Front Right // Repair-scratch



Roof // Smart Repair Medium-dent





Door Front Right // Smart Repair Medium-dent



Front Right Door Interior Coating // Replace Completely-scratch



Rocker Panel Right // Painting-scratch



Wheel Alloy Rear Right // Repair-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Wing Rear Left // Painting-scratch



Wheel Alloy Rear Left // Repair-scratch




Wing Front Left // Polish-scratch




Bumper Front / Grid Right / Replace-scratch




Bumper Front // Painting-scratch




Door Front Left // Smart Repair Small-scratch



Bumper Rear // Painting-scratch




Side View Mirror Right // Polish-scratch



Rear Bonnet / Rear Window / Replace-scratch




Door Rear Left // Polish-scratch



Central Console // Replace Completely-scratch



Wing Front right // Polish-scratch



Side View Mirror Left // Replace Not Painted-scratch




Side View Mirror Left / Direction Indicator / Replace-cracked



Side View Mirror Left / Shell / Replace Painted-cracked



Lettering Removal 15min-Remainder stickers



Wing Rear Right // Polish-bad repair



Door Rear Right // Polish-bad repair