

INSPECTION REPORT

End of contract

GENERAL INFO

File	317147
License plate	2DRS643
Vehicle identification number	VR3FRHNSLPY556532
Dossier	2022 188 230
Make	Peugeot 308 SW 1.2 130 Active
Mileage	54300
First registration	06/06/2023
client availability date	02/07/2026
inspectionDate	06/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	1	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
28	Front / Calendar / Replace	N
91	Rocker Panel Left // Smart Repair Medium	Y
133	Bumper Rear // Painting	Y
184	Wing Rear Right // Repair & Painting	N
311	Wheel Alloy Front Left // Repair	N
331	Wheel Alloy Rear Right // Repair	N
341	Wheel Alloy Front Right // Repair	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
883	Key Price Range 2 //	N

Damage Pictures



Bumper Rear // Painting-scratch



Wheel Alloy Front Left // Repair-scratch



Rocker Panel Left // Smart Repair Medium-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Wheel Alloy Rear Right // Repair-scratch



Wheel Alloy Front Right // Repair-scratch



Wing Rear Right // Repair & Painting-scratch + dent



Front / Calendar / Replace-cracked