

INSPECTION REPORT


End of contract

GENERAL INFO

File	317428
License plate	2CLR603
Vehicle identification number	W1N9M0JB6PN015443
Dossier	2022060077
Make	Mercedes EQB 300 4M Luxury Lin
Mileage	130455
First registration	07/09/2022
client availability date	06/07/2026
inspectionDate	10/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
16	Bumper Front // Polish	Y
67	Wing Front Left / Trim / Replace	Y
81	Door Front Left // Smart Repair Medium	N
91	Rocker Panel Left // Smart Repair Medium	N
106	Door Rear Left // Polish	Y
107	Door Rear Left / Trim / Replace	Y
110	Wing Rear Left // Smart Repair Small	Y
117	Wing Rear Left / Trim / Replace	Y
124	Light / Rear left / Replace	Y
133	Bumper Rear // Painting	Y
138	Bumper Rear / Lower Cover Not Painted / Replace	Y
150	Rear Bonnet // Smart Repair Small	Y
158	Rear Bonnet / 3rd Stoplight / Replace	N
174	Light / Rear Right / Replace	Y
186	Wing Rear Right // Polish	Y
196	Door Rear Right // Polish	Y
213	Door Front Right // Painting	Y
222	Side View Mirror Right // Painting	N
236	Wing Front right // Polish	Y
237	Wing Front right / Trim / Replace	Y
310	Wheel Two Tone Front Left // Repair	N
320	Wheel Two Tone Rear Left // Repair	N
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	N
411	Seat Front Left // Repair	N
421	Seat Front Right // Repair	N
533	Trunk Compartment / Side Cover Right / Replace	Y
540	Interior // Repair 1	Y
556	Central Console / Cover Armrest / Replace Cover Armrest	N
561	Dashboard // Repair	Y

569	Dashboard / Steering Wheel / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	N
638	Rear Left Door Interior Coating / Door Handle / Replace	Y
648	Rear Right Door Interior Coating / Door Handle / Replace	Y
774	Interior / Side Cover rear Seat / Replace	Y

Damage Pictures



Light / Rear left / Replace-scratch



Rear Bonnet / 3rd Stoplight / Replace-scratch



Light / Rear Right / Replace-scratch



Wheel Two Tone Rear Right // Repair-scratch



Wing Rear Right // Polish-scratch



Door Rear Right // Polish-scratch




Side View Mirror Right // Painting-scratch



Wheel Two Tone Front Right // Repair-scratch



Wing Front right / Trim / Replace-scratch



Wing Front right // Polish-scratch



Bumper Front // Polish-scratch



Wheel Two Tone Front Left // Repair-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Bumper Rear // Painting-scratch



Door Rear Left // Polish-scratch



Trunk Compartment / Side Cover Right / Replace-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Seat Front Right // Repair-scratch



Rear Right Door Interior Coating / Door Handle / Replace-scratch



Dashboard // Repair-scratch




Interior // Repair 1-scratch



Central Console / Cover Armrest / Replace Cover
Armrest-scratch



Seat Front Left // Repair-scratch



Interior / Side Cover rear Seat / Replace-scratch




Rear Left Door Interior Coating / Door Handle / Replace-scratch




Wheel Two Tone Rear Left // Repair-scratch





Door Rear Left / Trim / Replace-scratch




Wing Rear Left // Smart Repair Small-dent




Rear Bonnet // Smart Repair Small-dent



Door Front Left // Smart Repair Medium-scratch + dent



Rocker Panel Left // Smart Repair Medium-scratch + dent



Dashboard / Steering Wheel / Replace-worn



Door Front Right // Painting-Chipped paint



Wing Front Left / Trim / Replace-bad position



Wing Rear Left / Trim / Replace-bad position