

INSPECTION REPORT

End of contract

GENERAL INFO

File	315610
License plate	2CEC078
Vehicle identification number	W1K2062031F053915
Dossier	2021 320 085
Make	Mercedes C Break 200 d 120kW A
Mileage	91264
First registration	21/06/2022
client availability date	24/06/2026
inspectionDate	30/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	





DAMAGES

Damages	Type	Acceptable
12	Bumper Front // Smart Repair Large	N
38	Front Bonnet / Insulation / Replace	N
41	Windshield // Replace	Y
72	Side View Mirror Left // Painting	Y
136	Bumper Rear // Polish	Y
150	Rear Bonnet // Smart Repair Small	Y
211	Door Front Right // Smart Repair Medium	Y
272	Bumper Front / Trim Right / Replace	N
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	N
565	Dashboard / Storage Tray / Replace	Y

Damage Pictures



Dashboard / Storage Tray / Replace-scratch



Side View Mirror Left // Painting-scratch



Bumper Rear // Polish-scratch



Wheel Two Tone Rear Right // Repair-scratch



Door Front Right // Smart Repair Medium-scratch



Wheel Two Tone Front Right // Repair-scratch



Rear Bonnet // Smart Repair Small-dent



Bumper Front // Smart Repair Large-scratch + dent



Bumper Front / Trim Right / Replace-cracked



Front Bonnet / Insulation / Replace-tear



Windshield // Replace-stone chipping