

INSPECTION REPORT


End of contract

GENERAL INFO

File	317522
License plate	2DPG758
Vehicle identification number	VR3UPMHDP5041525
Dossier	2023027328
Make	Peugeot 208 1.2PT 75 Active Pa
Mileage	76059
First registration	12/05/2023
client availability date	20/07/2026
inspectionDate	28/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
134	Bumper Rear // Repair & Painting	N
138	Bumper Rear / Lower Cover Not Painted / Replace	N
40	Windshield // Repair	Y
124	Light / Rear left / Replace	Y
153	Rear Bonnet // Painting	N
314	Wheel Front Left / Wheel Cover / Replace	Y
324	Wheel Rear Left / Wheel Cover / Replace	N
334	Wheel Rear Right / Wheel Cover / Replace	N
344	Wheel Front Right / Wheel Cover / Replace	N
412	Seat Front Left / Bottom Coating / Replace	N
540	Interior // Repair 1	N
541	Interior // Repair 2	N
541	Interior // Repair 2	N

Damage Pictures



Rear Bonnet // Painting-bad repair



Windshield // Repair-cracked



Interior // Repair 2-Incinerated



Interior // Repair 2-Incinerated



Seat Front Left / Bottom Coating / Replace-Incinerated



Interior // Repair 1-missing



Light / Rear left / Replace-scratch



Wheel Rear Left / Wheel Cover / Replace-scratch



Wheel Front Left / Wheel Cover / Replace-scratch



Wheel Front Right / Wheel Cover / Replace-scratch



Wheel Rear Right / Wheel Cover / Replace-scratch



Bumper Rear // Repair & Painting-cracked



Bumper Rear / Lower Cover Not Painted / Replace-scratch + dent