

INSPECTION REPORT

End of contract

GENERAL INFO

File	316976
License plate	2CBZ405
Vehicle identification number	KMHC851CGNU287857
Dossier	2021319096
Make	Hyundai Ioniq 1.6GDi Hybride F
Mileage	124730
First registration	30/05/2022
client availability date	02/07/2026
inspectionDate	10/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
134	Bumper Rear // Repair & Painting	N
13	Bumper Front // Painting	N
63	Wing Front Left // Painting	N
801	See External Expertise	N
18	Bumper Front / Spoiler / Replace	Y
72	Side View Mirror Left // Painting	Y
84	Door Front Left // Repair & Painting	N
87	Door Front Left / Trim / Replace	Y
92	Rocker Panel Left // Painting	N
101	Door Rear Left // Smart Repair Medium	Y
110	Wing Rear Left // Smart Repair Small	Y
124	Light / Rear left / Replace	Y
156	Rear Bonnet // Polish	Y
174	Light / Rear Right / Replace	N
175	Light / Rear Right On Rear Bonnet / Replace	N
184	Wing Rear Right // Repair & Painting	N
194	Door Rear Right // Repair & Painting	Y
201	Rocker Panel Right // Smart Repair Medium	N
213	Door Front Right // Painting	Y
217	Door Front Right / Trim / Replace	Y
222	Side View Mirror Right // Painting	N
233	Wing Front right // Painting	N
311	Wheel Alloy Front Left // Repair	N
321	Wheel Alloy Rear Left // Repair	Y
331	Wheel Alloy Rear Right // Repair	N
341	Wheel Alloy Front Right // Repair	N
569	Dashboard / Steering Wheel / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
614	Front Left Door Interior Coating // Replace Completely	Y
631	Rear Left Door Interior Coating // Repair	Y

644	Rear Right Door Interior Coating // Replace Completely	Y
860	Interior Cleaning // Small	N

Damage Pictures



Door Rear Left // Smart Repair Medium-scratch + dent



Wheel Alloy Front Left // Repair-scratch



Wheel Alloy Rear Right // Repair-scratch



Door Front Right / Trim / Replace-scratch




Door Front Right // Painting-scratch



Wing Front right // Painting-scratch




Wheel Alloy Front Right // Repair-scratch




Side View Mirror Right // Painting-scratch




Side View Mirror Left // Painting-scratch




Door Front Left / Trim / Replace-scratch



Light / Rear left / Replace-scratch



Rear Bonnet // Polish-scratch




Light / Rear Right On Rear Bonnet / Replace-scratch



Light / Rear Right / Replace-scratch



Wheel Alloy Rear Left // Repair-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Rear Right Door Interior Coating // Replace Completely-scratch






Rear Left Door Interior Coating // Repair-scratch



Front Left Door Interior Coating // Replace Completely-scratch





Wing Rear Left // Smart Repair Small-dent



Door Front Left // Repair & Painting-scratch + dent



Wing Rear Right // Repair & Painting-scratch + dent



Door Rear Right // Repair & Painting-scratch + dent






Rocker Panel Right // Smart Repair Medium-scratch + dent



Rocker Panel Left // Painting-bad repair




Interior Cleaning // Small-stain






Dashboard / Steering Wheel / Replace-worn



Bumper Front / Spoiler / Replace-bad position




Bumper Rear // Repair & Painting-scratch + dent





See External Expertise-dent



Wing Front Left // Painting-scratch





Bumper Front // Painting-scratch