

INSPECTION REPORT



End of contract


GENERAL INFO

File	317521
License plate	2DPZ033
Vehicle identification number	VR3UPMHDP5041220
Dossier	2023027322
Make	Peugeot 208 1.2PT 75 Active Pa
Mileage	72255
First registration	22/05/2023
client availability date	20/07/2026
inspectionDate	29/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	





DAMAGES

Damages	Type	Acceptable
11	Bumper Front // Smart Repair Medium	N
38	Front Bonnet / Insulation / Replace	N
114	Wing Rear Left // Repair & Painting	N
133	Bumper Rear // Painting	N
138	Bumper Rear / Lower Cover Not Painted / Replace	Y
153	Rear Bonnet // Painting	N
203	Rocker Panel Right // Repair & Painting	N
234	Wing Front right // Repair & Painting	N
314	Wheel Front Left / Wheel Cover / Replace	N
324	Wheel Rear Left / Wheel Cover / Replace	N
334	Wheel Rear Right / Wheel Cover / Replace	N
344	Wheel Front Right / Wheel Cover / Replace	N

Damage Pictures



Wheel Rear Left / Wheel Cover / Replace-scratch




Wheel Front Left / Wheel Cover / Replace-scratch



Bumper Front // Smart Repair Medium-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Bumper Rear // Painting-scratch



Wheel Front Right / Wheel Cover / Replace-scratch



Wheel Rear Right / Wheel Cover / Replace-scratch




Wing Front right // Repair & Painting-dent



Wing Rear Left // Repair & Painting-dent



Rocker Panel Right // Repair & Painting-scratch + dent



Rear Bonnet // Painting-bad repair



Front Bonnet / Insulation / Replace-cracked