

INSPECTION REPORT

End of contract

GENERAL INFO

File	317586
License plate	1YPH948
Vehicle identification number	VR3FJEHYRLY025035
Dossier	2020 290 020
Make	Peugeot 508SW 2.0 BHDi GT Line
Mileage	107002
First registration	26/10/2020
client availability date	13/07/2026
inspectionDate	17/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
12	Bumper Front // Smart Repair Large	Y
72	Side View Mirror Left // Painting	Y
80	Door Front Left // Smart Repair Small	Y
104	Door Rear Left // Repair & Painting	N
110	Wing Rear Left // Smart Repair Small	Y
159	Rear Bonnet / Rear Window / Replace	Y
194	Door Rear Right // Repair & Painting	Y
214	Door Front Right // Repair & Painting	Y
222	Side View Mirror Right // Painting	Y
310	Wheel Two Tone Front Left // Repair	N
322	Wheel Alloy Rear Left // Replace	N
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	N
346	Tyre Front Right // Replace	Y
533	Trunk Compartment / Side Cover Right / Replace	Y
534	Trunk Compartment / Carpet / Replace	Y
540	Interior // Repair 1	N
541	Interior // Repair 2	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
773	Interior / A Pillar Lower Cover / Replace	Y
860	Interior Cleaning // Small	N

Damage Pictures



Door Front Left // Smart Repair Small-scratch



Side View Mirror Left // Painting-scratch



Wheel Two Tone Front Left // Repair-scratch



Bumper Front // Smart Repair Large-scratch



Tyre Front Right // Replace-scratch



Wheel Two Tone Front Right // Repair-scratch



Side View Mirror Right // Painting-scratch



Interior // Repair 2-scratch



Wheel Two Tone Rear Right // Repair-scratch



Rear Bonnet / Rear Window / Replace-scratch



Trunk Compartment / Side Cover Right / Replace-scratch



Trunk Compartment / Carpet / Replace-scratch




Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Interior / A Pillar Lower Cover / Replace-scratch



Wing Rear Left // Smart Repair Small-dent



Door Rear Left // Repair & Painting-scratch + dent




Wheel Alloy Rear Left // Replace-scratch + dent



Door Front Right // Repair & Painting-scratch + dent



Door Rear Right // Repair & Painting-scratch + dent



Interior Cleaning // Small-stain



Interior // Repair 1-bad position