

INSPECTION REPORT


End of contract

GENERAL INFO

File	318599
License plate	DH0211
Vehicle identification number	W1K1770141N292076
Dossier	2022032005
Make	Mercedes A 220 d 190 AMG Line
Mileage	78912
First registration	12/07/2022
client availability date	23/07/2026
inspectionDate	28/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	Y
159	Rear Bonnet / Rear Window / Replace	Y
180	Wing Rear Right // Smart Repair Small	Y
330	Wheel Two Tone Rear Right // Repair	N

Damage Pictures



Wheel Two Tone Rear Right // Repair-scratch



Rear Bonnet / Rear Window / Replace-scratch



Bumper Front // Painting-scratch



Wing Rear Right // Smart Repair Small-dent