

INSPECTION REPORT

End of contract

GENERAL INFO

File	315599
License plate	2ALN010
Vehicle identification number	W1N2476121W121057
Dossier	2020 314 061
Make	Mercedes GLB 200d Business Sol
Mileage	207881
First registration	04/05/2021
client availability date	01/07/2026
inspectionDate	16/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
67	Wing Front Left / Trim / Replace	N
80	Door Front Left // Smart Repair Small	Y
87	Door Front Left / Trim / Replace	N
91	Rocker Panel Left // Smart Repair Medium	Y
100	Door Rear Left // Smart Repair Small	Y
112	Wing Rear Left // Smart Repair Large	N
124	Light / Rear left / Replace	N
133	Bumper Rear // Painting	N
153	Rear Bonnet // Painting	N
159	Rear Bonnet / Rear Window / Replace	N
183	Wing Rear Right // Painting	N
193	Door Rear Right // Painting	N
214	Door Front Right // Repair & Painting	N
330	Wheel Two Tone Rear Right // Repair	Y
340	Wheel Two Tone Front Right // Repair	N
569	Dashboard / Steering Wheel / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y


Damage Pictures



Door Rear Left // Smart Repair Small-scratch



Door Front Left // Smart Repair Small-scratch




Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Wheel Two Tone Front Right // Repair-scratch




Wheel Two Tone Rear Right // Repair-scratch



Rear Bonnet / Rear Window / Replace-scratch



Rocker Panel Left // Smart Repair Medium-dent



Wing Rear Left // Smart Repair Large-dent



Bumper Rear // Painting-bad repair



Rear Bonnet // Painting-bad repair



Door Front Right // Repair & Painting-bad repair



Wing Rear Right // Painting-bad repair



Door Rear Right // Painting-bad repair



Door Front Left / Trim / Replace-cracked



Light / Rear left / Replace-cracked



Dashboard / Steering Wheel / Replace-scratch



Bumper Front // Painting-scratch



Wing Front Left / Trim / Replace-scratch