

INSPECTION REPORT

End of contract

GENERAL INFO

File	318888
License plate	NF0201
Vehicle identification number	TMAJE811BPJ212796
Dossier	2023219019
Make	Hyundai TUCSON T-GDI hyb 180 S
Mileage	35465
First registration	18/08/2023
client availability date	28/07/2026
inspectionDate	29/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
12	Bumper Front // Smart Repair Large	N
231	Wing Front right // Smart Repair Medium	N
80	Door Front Left // Smart Repair Small	Y
106	Door Rear Left // Polish	Y
138	Bumper Rear / Lower Cover Not Painted / Replace	Y
139	Bumper Rear / Spoiler / Replace	N
159	Rear Bonnet / Rear Window / Replace	N
196	Door Rear Right // Polish	Y
201	Rocker Panel Right // Smart Repair Medium	N
216	Door Front Right // Polish	Y
340	Wheel Two Tone Front Right // Repair	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y

Damage Pictures



Wheel Two Tone Front Right // Repair-scratch



Rocker Panel Right // Smart Repair Medium-scratch + dent



Door Front Right // Polish-scratch



Door Rear Right // Polish-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Rear Bonnet / Rear Window / Replace-scratch



Bumper Rear / Spoiler / Replace-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Door Rear Left // Polish-scratch



Door Front Left // Smart Repair Small-scratch



Bumper Front // Smart Repair Large-scratch



Wing Front right // Smart Repair Medium-scratch