

INSPECTION REPORT

End of contract

GENERAL INFO

File	311944
License plate	2ACV078
Vehicle identification number	NMTK33BX10R084966
Dossier	2021040122
Make	Toyota C-HR 1.8 Hybrid C-Lub M
Mileage	57242
First registration	23/02/2021
client availability date	05/05/2026
inspectionDate	29/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	





DAMAGES

Damages	Type	Acceptable
117	Wing Rear Left / Trim / Replace	N
133	Bumper Rear // Painting	N
85	Door Front Left // Replace & Painting	N
87	Door Front Left / Trim / Replace	N
98	Rocker Panel Left / Cover Not Painted / Replace	N
18	Bumper Front / Spoiler / Replace	N
274	Bumper Front / Grid Central / Replace	N
187	Wing Rear Right / Trim / Replace	N
194	Door Rear Right // Repair & Painting	N
18	Bumper Front / Spoiler / Replace	N
33	Front Bonnet // Repair & Painting	N
67	Wing Front Left / Trim / Replace	Y
78	Side View Mirror Left / Direction Indicator / Replace	N
103	Door Rear Left // Painting	Y
114	Wing Rear Left // Repair & Painting	Y
138	Bumper Rear / Lower Cover Not Painted / Replace	N
157	Rear Bonnet / Trim / Replace	Y
165	Roof // Polish	Y
174	Light / Rear Right / Replace	Y
183	Wing Rear Right // Painting	Y
205	Rocker Panel Right // Polish	Y
213	Door Front Right // Painting	N
234	Wing Front right // Repair & Painting	Y
237	Wing Front right / Trim / Replace	Y
310	Wheel Two Tone Front Left // Repair	N
320	Wheel Two Tone Rear Left // Repair	N
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	N
624	Front Right Door Interior Coating // Replace Completely	Y
860	Interior Cleaning // Small	N

Damage Pictures



Rocker Panel Right // Polish-scratch



Door Front Right // Painting-scratch



Wheel Two Tone Front Right // Repair-scratch



Wing Front right / Trim / Replace-scratch



Bumper Front / Spoiler / Replace-scratch



Wheel Two Tone Front Left // Repair-scratch



Door Rear Left // Painting-scratch



Rear Bonnet / Trim / Replace-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Light / Rear Right / Replace-scratch



Wing Rear Left // Repair & Painting-scratch + dent



Front Bonnet // Repair & Painting-scratch + dent



Wing Front right // Repair & Painting-scratch + dent



Wheel Two Tone Rear Left // Repair-scratch



Front Right Door Interior Coating // Replace Completely-scratch






Wing Rear Right // Painting-scratch



Wheel Two Tone Rear Right // Repair-scratch




Side View Mirror Left / Direction Indicator / Replace-cracked



Roof // Polish-Chemical reaction





Interior Cleaning // Small-stain




Wing Front Left / Trim / Replace-bad position




Bumper Rear // Painting-scratch



Wing Rear Left / Trim / Replace-scratch





Door Rear Right // Repair & Painting-scratch + dent



Wing Rear Right / Trim / Replace-scratch



Door Front Left // Replace & Painting-scratch + dent



Rocker Panel Left / Cover Not Painted / Replace-scratch



Door Front Left / Trim / Replace-scratch



Bumper Front / Spoiler / Replace-cracked



Bumper Front / Grid Central / Replace-cracked