

INSPECTION REPORT



End of contract

GENERAL INFO

File	315964
License plate	2ARZ341
Vehicle identification number	TMBJJ7NSSM8065034
Dossier	2021037023
Make	Skoda Kod.2.0CRTDI 110kW Cleve
Mileage	123394
First registration	28/06/2021
client availability date	01/07/2026
inspectionDate	14/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
133	Bumper Rear // Painting	N
138	Bumper Rear / Lower Cover Not Painted / Replace	N
197	Door Rear Right / Trim / Replace	Y
217	Door Front Right / Trim / Replace	Y
13	Bumper Front // Painting	Y
31	Front Bonnet // Smart Repair Small	Y
40	Windshield // Repair	Y
80	Door Front Left // Smart Repair Small	Y
89	Door Front Left / Window / Replace	Y
91	Rocker Panel Left // Smart Repair Medium	Y
106	Door Rear Left // Polish	Y
109	Door Rear Left / Window / Replace	Y
116	Wing Rear Left // Polish	Y
117	Wing Rear Left / Trim / Replace	Y
153	Rear Bonnet // Painting	Y
159	Rear Bonnet / Rear Window / Replace	N
181	Wing Rear Right // Smart Repair Medium	Y
194	Door Rear Right // Repair & Painting	Y
199	Door Rear Right / Window / Replace	N
213	Door Front Right // Painting	N
233	Wing Front right // Painting	N
271	Bumper Front / Trim Left / Replace	Y
321	Wheel Alloy Rear Left // Repair	Y
431	Seat Rear Left // Repair	Y
533	Trunk Compartment / Side Cover Right / Replace	Y
569	Dashboard / Steering Wheel / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
611	Front Left Door Interior Coating // Repair	N
624	Front Right Door Interior Coating // Replace Completely	Y
631	Rear Left Door Interior Coating // Repair	N

644	Rear Right Door Interior Coating // Replace Completely	Y
860	Interior Cleaning // Small	N

Damage Pictures



Door Rear Right / Window / Replace-scratch



Rocker Panel Left // Smart Repair Medium-scratch



Wing Rear Left / Trim / Replace-scratch



Wheel Alloy Rear Left // Repair-scratch



Wing Rear Left // Polish-scratch



Trunk Compartment / Side Cover Right / Replace-scratch




Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Rear Right Door Interior Coating // Replace Completely-scratch



Front Right Door Interior Coating // Replace Completely-scratch



Seat Rear Left // Repair-scratch




Rear Left Door Interior Coating // Repair-scratch




Dashboard / Steering Wheel / Replace-scratch



Front Left Door Interior Coating // Repair-scratch



Bumper Front / Trim Left / Replace-scratch




Bumper Front // Painting-scratch



Door Rear Left / Window / Replace-scratch



Door Rear Left // Polish-scratch




Door Front Left // Smart Repair Small-dent




Front Bonnet // Smart Repair Small-dent



Door Rear Right // Repair & Painting-scratch + dent



Door Front Right // Painting-bad repair



Wing Front right // Painting-bad repair



Windshield // Repair-glass damage



Interior Cleaning // Small-stain



Rear Bonnet / Rear Window / Replace-scratch



Wing Rear Right // Smart Repair Medium-scratch



Door Front Left / Window / Replace-scratch



Rear Bonnet // Painting-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Bumper Rear // Painting-scratch



Door Rear Right / Trim / Replace-scratch



Door Front Right / Trim / Replace-scratch