

INSPECTION REPORT

End of contract

GENERAL INFO

File	316487
License plate	1YCC499
Vehicle identification number	YV1PWADVDM1160288
Dossier	2020112029
Make	Volvo V90 D4 120 Momentum Pro
Mileage	164603
First registration	13/07/2020
client availability date	29/06/2026
inspectionDate	08/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES


Damages	Type	Acceptable
184	Wing Rear Right // Repair & Painting	N
194	Door Rear Right // Repair & Painting	N
125	Light / Rear Left On Rear Bonnet / Replace	Y
153	Rear Bonnet // Painting	Y
12	Bumper Front // Smart Repair Large	N
44	Windshield / Trim / Replace	Y
63	Wing Front Left // Painting	N
84	Door Front Left // Repair & Painting	Y
91	Rocker Panel Left // Smart Repair Medium	N
101	Door Rear Left // Smart Repair Medium	N
113	Wing Rear Left // Painting	N
124	Light / Rear left / Replace	N
134	Bumper Rear // Repair & Painting	N
139	Bumper Rear / Spoiler / Replace	N
174	Light / Rear Right / Replace	Y
201	Rocker Panel Right // Smart Repair Medium	Y
214	Door Front Right // Repair & Painting	Y
236	Wing Front right // Polish	Y
311	Wheel Alloy Front Left // Repair	N
321	Wheel Alloy Rear Left // Repair	N
331	Wheel Alloy Rear Right // Repair	N
341	Wheel Alloy Front Right // Repair	N
411	Seat Front Left // Repair	Y
421	Seat Front Right // Repair	N
533	Trunk Compartment / Side Cover Right / Replace	N
553	Central Console / Gear Lever / Replace	Y
554	Central Console // Replace Completely	Y
561	Dashboard // Repair	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
611	Front Left Door Interior Coating // Repair	N

631	Rear Left Door Interior Coating // Repair	N
641	Rear Right Door Interior Coating // Repair	N
773	Interior / A Pillar Lower Cover / Replace	Y

Damage Pictures




Light / Rear left / Replace-scratch




Light / Rear Right / Replace-scratch



Wheel Alloy Rear Right // Repair-scratch



Bumper Front // Smart Repair Large-scratch



Windshield / Trim / Replace-scratch




Wheel Alloy Front Right // Repair-scratch




Wing Front right // Polish-scratch



Interior / A Pillar Lower Cover / Replace-scratch



Dashboard // Repair-scratch



Wheel Alloy Rear Left // Repair-scratch




Wheel Alloy Front Left // Repair-scratch





Seat Front Left // Repair-scratch




Trunk Compartment / Side Cover Right / Replace-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch




Central Console // Replace Completely-scratch





Seat Front Right // Repair-scratch



Door Rear Left // Smart Repair Medium-dent





Rocker Panel Right // Smart Repair Medium-dent



Door Front Left // Repair & Painting-scratch + dent



Rocker Panel Left // Smart Repair Medium-scratch + dent





Wing Front Left // Painting-bad repair



Wing Rear Left // Painting-bad repair




Rear Left Door Interior Coating // Repair-tear



Rear Right Door Interior Coating // Repair-tear



Front Left Door Interior Coating // Repair-tear



Central Console / Gear Lever / Replace-worn



Bumper Rear / Spoiler / Replace-scratch + dent



Bumper Rear // Repair & Painting-scratch + dent




Door Front Right // Repair & Painting-scratch + dent



Wing Rear Right // Repair & Painting-scratch + dent





Door Rear Right // Repair & Painting-scratch + dent



Rear Bonnet // Painting-scratch



Light / Rear Left On Rear Bonnet / Replace-scratch