



ARVAL
BNP PARIBAS GROUP

2DNJ445

INSPECTION REPORT


End of contract


GENERAL INFO

File	318157
License plate	2DNJ445
Vehicle identification number	VF3VFEHS7N7077701
Dossier	2022 209 155
Make	Peugeot Expert 2.0BHDi 145 Sta
Mileage	87809
First registration	04/05/2023
client availability date	15/07/2026
inspectionDate	28/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	3	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
19	Bumper Front / Lower Cover Not Painted / Replace	Y
40	Windshield // Repair	Y
91	Rocker Panel Left // Smart Repair Medium	Y
138	Bumper Rear / Lower Cover Not Painted / Replace	Y
201	Rocker Panel Right // Smart Repair Medium	Y
293	Rear Loading Door Left // Painting	N
303	Rear Loading Door Right // Painting	N

Damage Pictures





Bumper Rear / Lower Cover Not Painted / Replace-scratch




Rocker Panel Left // Smart Repair Medium-scratch



Bumper Front / Lower Cover Not Painted / Replace-scratch



Rocker Panel Right // Smart Repair Medium-scratch + dent



Rear Loading Door Left // Painting-bad repair



Rear Loading Door Right // Painting-bad repair



Windshield // Repair-cracked