

INSPECTION REPORT


End of contract

GENERAL INFO

File	318716
License plate	PH9508
Vehicle identification number	VR3ECYHZRLJ838568
Dossier	2020 176 034
Make	Peugeot Rifter MWD HDi130 L AI
Mileage	52877
First registration	07/06/2021
client availability date	24/07/2026
inspectionDate	29/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	





DAMAGES

Damages	Type	Acceptable
11	Bumper Front // Smart Repair Medium	N
19	Bumper Front / Lower Cover Not Painted / Replace	N
272	Bumper Front / Trim Right / Replace	N
275	Bumper Front / Grid Right / Replace	N
152	Rear Bonnet // Smart Repair Large	N
197	Door Rear Right / Trim / Replace	N
210	Door Front Right // Smart Repair Small	N
314	Wheel Front Left / Wheel Cover / Replace	Y
317	Spare Wheel // Relpace	N
860	Interior Cleaning // Small	N

Damage Pictures



Door Front Right // Smart Repair Small-dent



Interior Cleaning // Small-stain



Door Rear Right / Trim / Replace-scratch



Rear Bonnet // Smart Repair Large-scratch



Wheel Front Left / Wheel Cover / Replace-scratch



Bumper Front / Trim Right / Replace-scratch



Bumper Front / Grid Right / Replace-scratch



Bumper Front / Lower Cover Not Painted / Replace-scratch



Bumper Front // Smart Repair Medium-scratch