

INSPECTION REPORT


End of contract

GENERAL INFO

File	316405
License plate	2APR373
Vehicle identification number	VF3MCYHZMMS148087
Dossier	2021041008
Make	Peugeot 5008 1.5BHDi 96kW GT
Mileage	101301
First registration	04/06/2021
client availability date	30/06/2026
inspectionDate	07/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
87	Door Front Left / Trim / Replace	Y
107	Door Rear Left / Trim / Replace	Y
16	Bumper Front // Polish	Y
54	Headlight / Front left / Replace	Y
18	Bumper Front / Spoiler / Replace	Y
33	Front Bonnet // Repair & Painting	Y
38	Front Bonnet / Insulation / Replace	N
86	Door Front Left // Polish	Y
91	Rocker Panel Left // Smart Repair Medium	N
100	Door Rear Left // Smart Repair Small	Y
116	Wing Rear Left // Polish	Y
124	Light / Rear left / Replace	Y
136	Bumper Rear // Polish	Y
153	Rear Bonnet // Painting	Y
163	Roof // Repair & Painting	N
174	Light / Rear Right / Replace	Y
186	Wing Rear Right // Polish	Y
196	Door Rear Right // Polish	Y
201	Rocker Panel Right // Smart Repair Medium	N
310	Wheel Two Tone Front Left // Repair	Y
320	Wheel Two Tone Rear Left // Repair	Y
330	Wheel Two Tone Rear Right // Repair	N
412	Seat Front Left / Bottom Coating / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
634	Rear Left Door Interior Coating // Replace Completely	N
644	Rear Right Door Interior Coating // Replace Completely	Y

Damage Pictures




Door Front Left // Polish-scratch



Door Rear Left // Smart Repair Small-scratch




Wheel Two Tone Rear Left // Repair-scratch



Wing Rear Left // Polish-scratch




Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Rear Right Door Interior Coating // Replace Completely-scratch




Rear Left Door Interior Coating // Replace Completely-scratch



Roof // Repair & Painting-dent



Rocker Panel Left // Smart Repair Medium-scratch + dent



Front Bonnet // Repair & Painting-scratch + dent



Rocker Panel Right // Smart Repair Medium-scratch + dent



Front Bonnet / Insulation / Replace-tear



Seat Front Left / Bottom Coating / Replace-tear



Rear Bonnet // Painting-scratch



Bumper Rear // Polish-scratch



Light / Rear left / Replace-scratch



Light / Rear Right / Replace-scratch




Wheel Two Tone Rear Right // Repair-scratch



Wing Rear Right // Polish-scratch



Door Rear Right // Polish-scratch



Wheel Two Tone Front Left // Repair-scratch



Bumper Front / Spoiler / Replace-scratch



Door Front Left / Trim / Replace-scratch



Door Rear Left / Trim / Replace-scratch



Bumper Front // Polish-scratch



Headlight / Front left / Replace-scratch