

INSPECTION REPORT

End of contract

GENERAL INFO

File	316458
License plate	2AMM913
Vehicle identification number	W1N2539131F966974
Dossier	2021 028 171
Make	Mercedes GLC 200d Bus.Sol.
Mileage	86583
First registration	17/05/2021
client availability date	01/07/2026
inspectionDate	04/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	







DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
67	Wing Front Left / Trim / Replace	N
801	See External Expertise	N
78	Side View Mirror Left / Direction Indicator / Replace	N
80	Door Front Left // Smart Repair Small	Y
91	Rocker Panel Left // Smart Repair Medium	N
106	Door Rear Left // Polish	Y
110	Wing Rear Left // Smart Repair Small	Y
117	Wing Rear Left / Trim / Replace	Y
133	Bumper Rear // Painting	N
138	Bumper Rear / Lower Cover Not Painted / Replace	Y
159	Rear Bonnet / Rear Window / Replace	Y
161	Roof // Smart Repair Medium	Y
174	Light / Rear Right / Replace	Y
180	Wing Rear Right // Smart Repair Small	Y
194	Door Rear Right // Repair & Painting	Y
205	Rocker Panel Right // Polish	Y
214	Door Front Right // Repair & Painting	N
230	Wing Front right // Smart Repair Small	N
310	Wheel Two Tone Front Left // Repair	N
316	Tyre Front Left // Replace	Y
320	Wheel Two Tone Rear Left // Repair	N
330	Wheel Two Tone Rear Right // Repair	Y
340	Wheel Two Tone Front Right // Repair	N
538	Trunk Compartment / Boot Cover / Replace	Y

Damage Pictures



Wing Rear Left // Smart Repair Small-dent



Door Front Left // Smart Repair Small-dent





Wing Front right // Smart Repair Small-dent





Roof // Smart Repair Medium-dent



Wing Rear Right // Smart Repair Small-dent



Door Rear Right // Repair & Painting-scratch + dent



Door Front Right // Repair & Painting-scratch + dent



Rocker Panel Left // Smart Repair Medium-scratch + dent



Tyre Front Left // Replace-tear



Wheel Two Tone Front Left // Repair-scratch



Side View Mirror Left / Direction Indicator / Replace-scratch



Wing Rear Left / Trim / Replace-scratch



Wheel Two Tone Rear Left // Repair-scratch



Door Rear Left // Polish-scratch



Trunk Compartment / Boot Cover / Replace-scratch






Bumper Rear / Lower Cover Not Painted / Replace-scratch



Bumper Rear // Painting-scratch



Rear Bonnet / Rear Window / Replace-scratch



Light / Rear Right / Replace-scratch



Wheel Two Tone Rear Right // Repair-scratch



Rocker Panel Right // Polish-scratch



Wheel Two Tone Front Right // Repair-scratch







Wing Front Left / Trim / Replace-scratch



Bumper Front // Painting-scratch





See External Expertise-dent